



TERRAZZO
Resinous, Magnesite or Oxychloride

Scrub with a solution of SUPER SHINE-ALL®. Rinse thoroughly and let dry at least one hour. Apply two coats of ONEX-SEAL® II according to manufacturer's label directions.